

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Harvey A. Pugh House (William Saxton House)  
East side of N. Broadway St.  
Montour  
Gem County  
Idaho

HABS No. ID-41

HABS

ID

23-MONT,

9A-

Elevator, Mill & Warehouse

- ID-41-A-1      GENERAL EXTERIOR VIEW OF WEST & SOUTH ELEVATIONS, LOOKING NORTH-NORTHEAST, (Hans Muessig, Photographer, March 1979)
- ID-41-A-2      EXTERIOR, NORTH ELEVATION  
(Robert Ryan, Photographer, April 1979)
- ID-41-A-3      EXTERIOR, SOUTH & EAST ELEVATIONS, LOOKING NORTHWEST  
(Robert Ryan, Photographer, April 1979)
- ID-41-A-4      EXTERIOR, SOUTH ELEVATION OF CONCRETE SECTION  
(Robert Ryan, Photographer, April 1979)
- ID-41-A-5      INTERIOR, BAGGING ROOM, LOOKING NORTHWEST  
(Sarah Dennett, Photographer, April 1979)
- ID-41-A-6      INTERIOR OF SILO SECTION, LOOKING NORTHWEST  
(Sarah Dennett, Photographer, April 1979)
- ID-41-A-7      WAREHOUSE INTERIOR, LOOKING EAST  
(Sarah Dennett, Photographer, April 1979)